


- 1 Split-point tip for starting holes exactly where you need them
- 2 High-speed steel (HSS) for strength and resistance to heat



Video



BOSCH

